

Inspection Photos
Operator: Simcoe
API: 067-07186
Date: 2/11/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Vegetation is in a grazed and dormant condition at this time.



Photos 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of the reference area comprised of pinyon/juniper woodland with understory of sagebrush, antelope bitterbrush, gambel oak, and blue grama.