

Inspection Photos
Operator: Simcoe
API: 067-09467
Date: 2/11/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing with crested wheatgrass, smooth brome, and western wheatgrass.



Photos 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4 View of the reference area comprised of irrigated grass field in dormant vegetative condition.



Photos 5/6. View of closed gates after leaving location.