

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/17/2021

Submitted Date:

02/17/2021

Document Number:

699502290

FIELD INSPECTION FORM
 Loc ID 318073 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10536

Name of Operator: SMITH ENERGY LLC

Address: 1540 MAIN ST SUITE 218 #334

City: WINDSOR State: CO Zip: 80550

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Deranleau, Greg		greg.deranleau@state.co.us	
Smith, Glen		smithenergy@live.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240556	WELL	PR	04/01/1985	OW	123-08344	SCHEID-COOKSEY 1	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type LOCATION

Comment: 4' barb wire / electric cattle fence

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

1

Comment: electric / automation

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

1

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: gas motor

Inspected FacilitiesFacility ID: 240556 Type: WELL API Number: 123-08344 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 06/25/2020Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 10

Comment: Separator line froze and burst. At time of inspection company representative was on location addressing issue.

Corrective Action: Control and contain spills/releases and clean up per COGCC rules. Contact COGCC EPS staff.

Date: 02/17/2021

Reportable: YES

GPS: Lat Long

Proximity to Surface Water: 200

Depth to Ground Water:

Water Well Complaint:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location: Comment:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 1/16/21 at approximately 1400 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Scheid Cooksey 1</p> <p>Company Name- Smith Energy</p> <p>API- 05-123-08344</p> <p>In Weld County Colorado.</p> <p>While there, I observed PR well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Separator line froze and burst. At time of inspection company representative was on location addressing issue.</p> <p>Control and contain spills/releases and clean up per COGCC rules. Contact COGCC EPS staff. 2/17/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection company representative was actively addressing line leak with vacuum truck, and other equipment. Company representative informed me that the leak was only produced water at that point. Hydrocarbon smell was present while on location by separator. I informed the company representative that they will need to file a form 19 to inform the COGCC of the issues on location, and was told they will perform this when they are done containing the issues.</p> <p>At time of inspection weather conditions were cold, overcast, recent snow, slight wind.</p> <p>At time of inspection unable to access wellhead due to vacuum truck blocking entrance, electrified cattle fence, and cattle near entrance to access road.</p> <p>This is a summary of inspection report.</p>	medinaj	02/17/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699502291	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5353611