

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/17/2021

Submitted Date:

02/17/2021

Document Number:

699502292**FIELD INSPECTION FORM**
 Loc ID 318082 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10536Name of Operator: SMITH ENERGY LLCAddress: 1540 MAIN ST SUITE 218 #334City: WINDSOR State: CO Zip: 80550**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Glen		smithenergy@live.com	
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240573	WELL	PR	04/01/1985	OW	123-08361	SCHEID-COOKSEY 2	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment: gas motor

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 240573 Type: WELL API Number: 123-08361 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 06/25/2020Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

At time of inspection location appears to be in compliance with COGCC rules.  
 At time of inspection unable to reach wellhead due to spill mitigation in progress on tank battery, cattle, and electrified fence around location.  
 At time of inspection company representative informed me that base beam from workover rig was still on location but was going to be removed this week.  
 At time of inspection weather conditions were cold, slight wind, overcast, recent snow.

medinaj

02/17/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502293	Pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5353612">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5353612</a>