

# *Inspection Photos*

*Loc#3241032*

*Operator: Terra*

*Inspection Number: 692403022*

*Inspection Date: 2/10/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

View over Location to Southeast. Note unchecked stormwater/sediment flow off pad.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#324102



Photo#2:  
Sediment trap.



Photo#3:  
BMPs being undercut by stormwater flow.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#324102





Photo#4:  
BMPs being undercut by stormwater flow.



Photo#5:  
BMPs being undercut by stormwater flow.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#324102





Photo#6:  
BMPs being undercut(scoured/eroded) by stormwater flow.

February 10, 2021



Photo#7:  
BMPs being undercut(scoured/eroded) by stormwater flow.





Photo#6:  
Culvert on access road.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#7:  
Sediment deposition downstream of  
culvert.

Inspection Photos: Terra Clough Loc#324102





Photo#8:  
Slope that will need to be stabilized.



Photo#9:  
Tamarisk along access road.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#324102