

CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335814



**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335814**



Location shows signs of lack of stabilization BMP's in some areas (rutting is present).



Access road shows signs of lack of stabilization BMP's in some areas (rutting is present).

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335814**



Culvert inlet at entrance of location.



Culvert outlet at entrance of location.

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335814**



**Storm water not draining to culvert at
entrance of location.**



**Storm water not draining to culvert at
entrance of location.**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335814**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335814**



N39.55096 W108.12064

Water not draining off road into culvert or ditch.



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335814



N39.55334 W108.11990

Erosion damage from culvert outlet. Access road shows signs of lack of stabilization BMP's in some areas (rutting is present).



N39.55334 W108.11990

Erosion damage from culvert outlet.

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335814**



Erosion damage from culvert outlet.



Erosion has exposed pipe line.

CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335814

