



40.09782, -108.85575, 5153.9ft, 56°
02/17/2021 01:25:56 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Pump jack.

McLaughlin SR 6

API: 05-103-05500

Inspection: 700405446



40.0978, -108.85572, 5152.4ft, 31°
02/17/2021 01:26:06 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Oil spill.

McLaughlin SR 6

API: 05-103-05500

Inspection: 700405446



40.09781, -108.85563, 5155.5ft, 330°
02/17/2021 01:27:01 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Venting.

McLaughlin SR 6

API: 05-103-05500

Inspection: 700405446