



40.06863, -108.79396, 5364.1ft, 299°
02/17/2021 01:46:51 PM




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.


Arrowhead 9

API: 05-103-05301

Inspection: 700405450



40.06873, -108.79405, 5370.6ft, 85°
02/17/2021 01:47:59 PM



40.06873, -108.79405, 5369.3ft, 50°
02/17/2021 01:53:31 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well gas leak

Arrowhead 9

API: 05-103-05301

Inspection: 700405450



40.06922, -108.79438, 5365.8ft, 176°
02/17/2021 01:49:20 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tank.

Arrowhead 9

API: 05-103-05301

Inspection: 700405450



40.06866, -108.79412, 5370.7ft, 319°
02/17/2021 01:47:22 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Debris.

Arrowhead 9

API: 05-103-05301

Inspection: 700405450