

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/17/2021

Submitted Date:

02/18/2021

Document Number:

700405446**FIELD INSPECTION FORM**Loc ID 311791 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Heil, John		john.heil@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Boulger, Levin		lboulger@31operating.com	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228594	WELL	SI	12/01/2019	OW	103-05500	MCLAUGHLIN SR 6	SI

General Comment:

A follow up inspection of documents:

- 1) FIR 700404645 dated 12-18-2020.
- 2) FIR 700404676 dated 12-21-2020.
- 3) FIR 699700239 dated 12-23-2020.
- 3) FIR 700404795 dated 12-28-2020.

The following compliance issues are uncompleted:

- 1) Report past due monthly operations on Form 7. Complete by 1-11-2021.
- 2) Clean up the oil spill and contact the COGCC EPS staff in reference to the oil spill. Photos 2, 3, 4. Complete by 12-19-2020.
- 3) Gas venting out casing open to the atmosphere. Photo 5. Complete by 2-18-2021.

The emergency number 800-209-9762 was called on 2-18-2021 @ 10:32 to report the venting gas.

Well is located within a CDPHE Reg 42 limited use & quality area, a Rule 1202.c sport fish management area, and a Rule 1202.d pronghorn winter concentration area, 600' from a business, and 1650' from a residence.

This is a summary of inspection report 700405446.

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
Crude Oil				
Comment:	Spill is not cleaned up. Spill was contained.			
Corrective Action:	Clean up per Rule 912. Contact COGCC EPS staff.			Date: 12/19/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Dirt base.				
Corrective Action:				Date:

Venting:

Yes/No	YES		
Comment:	Gas venting out open casing. Gas odor on location. See attached FLIR videos & pictures.		
Corrective Action:	Comply with Rule 903.d.(3) for venting of gas.	Date:	02/18/2021

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 228594 Type: WELL API Number: 103-05500 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations. The well was producing until 12-21-2020 when the inspector shutoff the power at the panel to stop the spill.

Corrective Action: Submit required Form 7(s) to COGCC.

Date: 01/11/2021

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: 1" of snow on location.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Calm Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
1:25	PM	1:35	PM	Wellhead(s)

Comment: FLIR camera used to image venting of gas from the open casing. See attached videos.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700405447	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354830
700405448	FLIR HSM video of gas venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354831
700405449	FLIR video of gas venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354832