

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/18/2021

Submitted Date:

02/18/2021

Document Number:

699303510

FIELD INSPECTION FORM
 Loc ID 336536 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297348	WELL	SI	08/01/2020	GW	123-27078	PIONEER 21-14	SI

General Comment:

Location**Lease Road:**

Type	Access		
comment:	well site is in a corn field		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	location entrance signs are adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 297348 Type: WELL API Number: 123-27078 Status: SI Insp. Status: SI

CementCement ContractorContractor Name: Schlumberger

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): CICR 1568Cement Volume (sx): 214 sxsGood Return During Job: YESCement Type: G

Comment: Arrived on location @ 1155 hrs Schlumberger cement equip. rigged up ready, Mix and pump 214 sxs (47 bbl) 15.8 lbs. Type G cement for squeeze @ 2000 ft. CICR set @ 1568 ft. with good returns to circulation tanks, equipment grounded and looks to be in compliance with COGCC rules.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 02/18/2021 at approximately 1150 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Pioneer 21-14 at API #05-123-27078</p> <p>in Weld County Colorado.</p> <p>While there, I observed a Plugging Operation, all equipment is grounded and looks to be in compliance with COGCC Rules.</p> <p>During this inspection no compliance issues were observed:</p> <p>See attached photos.</p> <p>Location: Muddy with some snow, Weather: partly cloudy and cold.</p> <p>I spoke with Domingo DeLapaz Wellsite Supervisor for Kerr McGee about current operations, cement volume, type, weight, perf depths, CICR depth.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	02/18/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303511	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5355356