

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2021

Submitted Date:

02/12/2021

Document Number:

696202322**FIELD INSPECTION FORM**

Loc ID 323798	Inspector Name: Trujillo, Aaron	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 6 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>16700</u> Name of Operator: <u>CHEVRON USA INC</u> Address: <u>100 CHEVRON ROAD</u> City: <u>RANGELY</u> State: <u>CO</u> Zip: <u>81648</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
Patterson, Chris		spwu@chevron.com	All Inspections per Olson
Olson, Andrew		andrewolson@chevron.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159256	UIC DISPOSAL	CL	11/04/2013		-	CHEVRON 3-17E	RI
210833	WELL	PA	11/04/2013	DSPW	045-06591	SKINNER RIDGE 3-17E	RI
323798	LOCATION	CL			-	SKINNER RIDGE-65S98W 17SENE	RI

General Comment:

On 2/8/2021, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at Chevron USA's Chevron Skinner Ridge 3-17E location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:
1004.a: Final Reclamation

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected FacilitiesFacility ID: 159256 Type: UIC API Number: - Status: CL Insp. Status: RIFacility ID: 210833 Type: WELL API Number: 045-06591 Status: PA Insp. Status: RIFacility ID: 323798 Type: LOCATION API Number: - Status: CL Insp. Status: RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed Fail No disturbance /Location never built _____

Access Roads Regraded Fail Contoured Fail Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured Fail

Compaction alleviation Fail Dust and erosion control _____

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: [See "COGCC Comments" for comments regarding final reclamation.](#)

Corrective Action: _____ Date _____

Conduct final reclamation in accordance with Rule 1004.a: Remove surface equipment, utility equipment, and debris remaining on the Location; Conduct compaction alleviation pursuant to Rule 1003.c; Recontour/regrade Location and access road and conduct revegetation activities; Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Overall Final Reclamation

Fail

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Ensure that adequate stormwater and erosion controls are implemented prior to major earth-moving final reclamation activities on the Location, and that BMPs are maintained in proper functioning condition per good engineering practices; Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage stormwater and erosion on Location until Final Reclamation has passed.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Form 6(s) 400516384 states well was plugged 11/4/2013. Pursuant to Rule 1004.a, all debris and surface equipment shall be removed within 3 months of plugging a well, and all reclamation work is required to be completed within 12 months on non-crop land.	trujilloam	02/12/2021
It was observed in this inspection that Location is out of compliance with COGCC Final Reclamation requirements; Various debris, fence equipment, utility equipment, shed/building, and signage remain on the Location. All surface equipment, trash, debris, etc... was required to be removed from the Location by 2/4/2014.		
Final reclamation not performed; Location and access road have not been recontoured/regraded and reclaimed; Cut and fill slopes remain. All reclamation work pursuant to Rule 1004.a was required by 11/4/2014; Location is at least 6 years out of compliance.		
Due to the significant nature, extent, or duration of this alleged rule violation, no corrective action date will not be applied and Location will remain out of compliance until final reclamation work has been completed pursuant to COGCC 1004 Rules.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402598956	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351282
696202323	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351280