

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/03/2021

Submitted Date:

02/12/2021

Document Number:

700405309**FIELD INSPECTION FORM**Loc ID 336391 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Boulger, Levin		lboulger@31operating.com	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231796	WELL	SI	07/01/2017	GW	103-09467	FEE M-31-2-96N	SI
270739	WELL	SI	05/01/2020	GW	103-10406	ANT HILL UNIT RBCWG 6-11D	SI

General Comment:

A follow up inspection of FIR documents:

- 1) Warning letter 402270422 dated 12-23-2019.
- 2) 679706682 dated 12-26-2019.
- 3) 679707017 dated 1-16-2020.
- 4) 700702074 dated 12-28-2020.

The following compliance issues are uncompleted:

- 1) Acquire or MIT or plug well 05-103-09467. Photo 2. Complete by 3-31-2020.
- 2) Debris on location. Photos 1 to 6. Complete by 2-1-2021.

Additional compliance issues:

- 1) Submit Form 7 to report current well status & volumes. Complete by 2-26-2021.
- 2) Provide bradenhead access on well 05-103-10406. Photo 3. Complete by 3-14-2021.

This is a summary of inspection report 700405309.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Remove debris.	Date:	02/01/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 2	
Comment:	Telemetry.	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	Bradenhead access is not present on well 05-103-10406.	
Corrective Action:	Provide bradenhead access with appropriate fittings to allow determination of pressure and fluid flow.	Date: 03/14/2021
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	Tank sounded empty.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent		Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	Tank sounded empty.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 231796 Type: WELL API Number: 103-09467 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last reported production June 2017.

Corrective Action: Well must be either:

Date: 03/31/2020

1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or

2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Facility ID: 270739 Type: WELL API Number: 103-10406 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last reported production September 2019.

Last reported monthly operations were for June 2020 on both wells. Report past due monthly operations & volumes.

Corrective Action: Submit required Form 7(s) to COGCC.

Date: 02/26/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				

Comment: 8" of snow on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402599161	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351466
700405310	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351457