

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/18/2021

Submitted Date:

02/19/2021

Document Number:

688309744**FIELD INSPECTION FORM**Loc ID 317060 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 24500Name of Operator: PADCO LLCAddress: 800 W 6TH STREET SUITE 1010City: LOS ANGELES State: CA Zip: 90017**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|----------------|--|--------------------------|
| Crumley, Tim | (970) 768-5658 | tcrumley@tcrumleypumpingse vice.com | Pumper |
| Richmond, Dan | (918) 630-9912 | dan@dsrinc.net | Field Operations Manager |
| Young, Rob | | rob.young@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 235585 | WELL | PR | 06/01/2020 | OW | 121-08075 | VENRICK 2-A | SI |

General Comment:

Part of Venrick 1A spill inspection, oil at wellhead, wellhead leaking (inspector left message with operator)

LocationOverall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-768-5639

Corrective Action:

Date: _____

Overall Good: ☐

| | | | | | |
|--------------------|--|----------|--|-------|------------|
| Spills: | | | | | |
| Type | Area | Volume | | | |
| Crude Oil | WELLHEAD | <= 1 bbl | | | |
| Comment: | Stuffing box leak, fix, water still running at time of inspection | | | | |
| Corrective Action: | Per Rule 608e. Mechanical Conditions. All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition. All equipment will be engineered, operated, and maintained within the manufacturer's recommended specifications. | | | Date: | 03/19/2021 |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 235585 Type: WELL API Number: 121-08075 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 688309747 | PADCO Venrick 2-A | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5355626 |