

Inspection Photos
Operator: Hilcorp Energy
API: 067-09370
Date: 2/11/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation appears to be progressing with western wheatgrass and crested wheatgrass observable.



Photos 3. View of the southern interim reclamation area, surface owner equipment appears to be moved off of the reclamation area.



Photo 4. View of the reference area comprised of irrigated grass fields, with smooth brome observable.