

Inspection Photos

Operator: Rim Operating
API: 067-09277
Date: 2/11/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope facing westward. Reclamation areas are vegetated with rubber rabbitbrush and crested wheatgrass.



Photo 3. View of the reference area comprised of sagebrush shrubland. Understory vegetation not observable at this time.