

Inspection Photos  
Operator: Simcoe  
API: 067-06663  
Date: 2/11/2021



Photo 1. View of the project area from the southern corner facing center.



Photo 2. View of the southern fill slope facing eastward. Revegetation is grazed and dormant at this time. However, it is evident that portions of the fill slope are bare. Revegetation needs to be monitored during the active growing season and seeding conducted where vegetation is not becoming established.



Photo 3. View of the reference area comprised of open grass field, largely snow covered at this time.





Photo 4. View of closed gate after leaving location.