

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/19/2021

Submitted Date:

02/22/2021

Document Number:

696202348**FIELD INSPECTION FORM**Loc ID 314804 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Olson, Andrew		andrewolson@chevron.com	Principal Agent
Patterson, Chris		spwu@chevron.com	All Inspections per Olson

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229626	WELL	SI	06/18/1998	ERIW	103-07283	CARNEY C T 24X35	RI
314804	LOCATION	AC			-	CARNEY C T-62N102W 35NWNE	RI

**General Comment:**

On 2/19/2021, Reclamation Specialist Trujillo conducted a stormwater inspection at Chevrns USA Inc's CARNEY C T #24X35 location in Rio Blanco County, Colorado.

The following compliance issues were observed during this inspection:

1002.f.: Stormwater Management

606: Good Housekeeping

Refer to the "Good Housekeeping" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	TRASH		
Comment:	Various cable and wood debris observed on the west end of the Location.		
Corrective Action:	Comply with Rule 606 and remove trash debris.		Date: 03/22/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	229626	Type:	WELL	API Number:	103-07283	Status:	SI	Insp. Status:	RI
Facility ID:	314804	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: It was observed that stormwater and erosion control measures to protect the slopes, and to allow for sediment laden-free stormwater discharge are missing, or insufficient; Runoff causing gulley erosion on the northeast corner of the Location; slopes along western end of the Location bare/exposed; degradation evident.

Corrective Action: Comply with Rule 1002.f.(2)C and install required stormwater and erosion control BMPs; ensure control measures are adequate for the site's conditions, installed in accordance with good engineering practices, and are maintained in a proper functioning condition.

Date: 03/22/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202349	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5357913">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5357913</a>