

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLY-67S95W /11SESE

Location ID: 324238



Photo #2942 from entrance to location.



Photo #2943 from entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLY-67S95W /11SESE

Location ID: 324238



**Photo #2944 Multiple flow line heating insulation open ended and not capped.**



**Photo #2945 Multiple flow line heating insulation open ended and not capped.**