

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2021

Submitted Date:

02/23/2021

Document Number:

698600592**FIELD INSPECTION FORM**Loc ID 319709 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201052	WELL	SI	06/01/2017	OW	001-06455	STATE OF COLORADO AB 1	PA

**General Comment:**

This is an orphaned well inspection. Inspection completed to document well plug and abandonment work accomplished 1/28/2021 – 2/09/2021. Previous FIR document number 698600576 documents equipment decommissioning/removal and flowline abandonment/removal.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable documents and pictures.

**Inspected Facilities**Facility ID: 201052 Type: WELL API Number: 001-06455 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: Bolher ServicesContractor Phone: 970-522-3078Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: YES

Cement Type: \_\_\_\_\_

Comment: Well plug and abandonment work has been completed. See attached daily reports for plug placement and cement details.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Well plug and abandonment work has been completed with surface casing cut off 6' below grade and marker plate welded onto surface casing.	stjohnw	02/23/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600593	Daily Report 20210129	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358328">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358328</a>
698600594	Daily Report 20210201	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358329">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358329</a>
698600596	Daily Report 20210203	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358330">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358330</a>
698600597	Daily Report 20210202	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358331">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358331</a>
698600598	Daily Report 20210204	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358332">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358332</a>
698600599	Daily Report 20210209	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358333">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358333</a>