

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2021

Submitted Date:

02/22/2021

Document Number:

701101189**FIELD INSPECTION FORM**Loc ID 336047 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|-----------------|
| Sanford, Anita | (970) 675-3842 | atlx@chevron.com | All Inspections |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |

General Comment:

I, Inspector Mike Longworth, conducted an inspection at Chevron USA INC, SKINNER RIDGE-65S98W 25NENW, Location # 336047 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

Location sign is illegible.

Location id # is not on sign.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Location sign is illegible. Sign needs update to Comply with 605.a.(2). Location id # is not on sign. | | |
| Corrective Action: | Comply with Rule 605.g.(2) and 605.a.(2) | Date: | 05/23/2021 |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|-----|-------------|
| Emergency Contact Number: | | |
| Comment: | 911 | |
| Corrective Action: | | Date: _____ |

| | | | |
|---------------------------|-------|-------|--|
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 20 | | |
| Comment: | Braden head accessible for monitoring. | | |
| Corrective Action: | | Date: | |

| | | |
|--------------------|--|-------|
| Type: Plunger Lift | # 20 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bradenhead | # 3 | |
| Comment: | Braden head accessible for monitoring. | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | Compaction | | | | |
| Ditches | | | | | | |
| Check Dams | | | | | | |
| Berms | | | | | | |
| Drains | | | | | | |
| | | Culverts | | | | |
| | | | | Material Handling And Spill Prevention | | |
| | | | | | | |
| Compaction | | | | | | |
| | | Ditches | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 701101190 | Inspection 701101189 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5358378 |