

Inspection Photos

2/19/2021

Operator: CHEVRON USA INC - 16700

Location ID: 398284

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398284



Photo 1: Photo taken east of the well site, facing west. Photo shows well marker.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398284



Photo 2: Photo taken west of the well site, facing east. Photo shows well marker and Location.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398284



Photo 3: Photo taken from the southern areas of the Location, facing south. Photo shows areas of the Location where vegetative establishment is not occurring, and stormwater and erosion control measures are missing or insufficient to stabilize soils.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398284



Photo 4: Photo taken from the southern areas of the Location, facing east. Photo shows stormwater and erosion control measures are missing or insufficient to stabilize soils.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398284



Photo 5: Photo taken from the southwestern areas of the Location, facing southwest. Photo shows cable debris remaining on the Location.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398284



Photo 6: Photo taken from the southern areas of the Location, facing north. Photo shows stormwater and erosion control measures are missing or insufficient to stabilize soils.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398284



Photo 7: Photo taken from the southern areas of the Location, facing east. Photo shows stormwater and erosion control measures are missing or insufficient to stabilize soils.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398284



Photo 8: Photo taken from the southern areas of the Location, facing north. Photo shows stormwater and erosion control measures are missing or insufficient to stabilize soils.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 398284



Photo 9: Photo taken from the southern areas of the Location, facing north. Photo shows large areas of the Location where desirable vegetative establishment is not evident.