

Inspection Photos

2/19/2021

Operator: CHEVRON USA INC - 16700

Location ID: 314658

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314658



Photo 1: Photo taken from the access road north of the Location, facing south. Photo provides and overview of the Location/reclamation area.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314658



Photo 2: Photo taken from the north end of the Location, facing southeast. Photos 2-4 provide an overview of the Location from southeast, south to southwest.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314658



Photo 3: See comments under photo 2



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314658



Photo 4: See comments under photo 2.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314658



Photo 5: Photo taken from the southwest end of the Location, facing east. Photo shows stormwater and erosion control measures are missing, or insufficient to stabilize the soils and manage runoff from the Location.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314658



Photo 6: Photo taken from the east end of the Location, facing west. Photo shows stormwater and erosion control measures are missing, or insufficient to stabilize the soils and manage runoff from the Location; Operator appears to have only installed surface roughening (tracking) on the Location, no additional BMPs have been installed in conjunction with surface roughening; photo also shows that tracking has been installed perpendicular to the contours of the land, and not parallel in accordance with good engineering practices.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314658



Photo 7: Photo taken from the reast end of the Location, facing north. Photo shows stormwater and erosion control measures are missing, or insufficient to stabilize the soils and manage runoff from the Location.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314658



20210219

Photo 8: Close up photo of the soil surface of the Location. Unable to find evidence that seeding activates have been conducted.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314658




Photo 9: Photo taken from the west end of the Location, facing west. Photo shows operator has installed surface roughening (tracking) along the western slopes. Tracking has been installed in accordance with good engineering practices (parallel to the contours). However tracking is a temporary measure that should be used in conjunction with other erosion and sediment controls; no other erosion and sediment control measures observed on Location.

