

# Inspection Photos

2/19/2021

Operator: CHEVRON USA INC - 16700

Location ID: 314707

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 1:** Photo taken from the access road east of the Location, facing southwest. Photo 1-3 provide an overview of the Location/reclamation area from southwest to northwest.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 4:** Photo taken from the slopes on the east end of the disturbance area/Location. It was observed that drill seeding appears to have been conducted on the Location. Photo shows an example of slopes observed on the Location where drill seeding, or broadcast seeding is not evident; uniform revegetation activities do not appear to have been conducted. Photo also shows that stormwater and erosion control measures are missing, or insufficient to stabilize the soils and manage runoff from the Location.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 5:** Photo taken upslope/northwest of photo #4. Photo shows evidence of drill seeding on the Location. Photo also shows that stormwater and erosion control measures are missing, or insufficient to stabilize the soils and manage runoff from the Location.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 6:** Photo taken from the northeast end of the Location, facing southwest. See comments under photo 6.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 7:** Photo taken from the west end of the Location, facing southwest. See comments under photo #4 regarding uniform revegetation activities and stormwater/erosion control management.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 8:** Photo taken from the west end of the Location, facing east. Photo looking up the slopes in photo #7. See comments under photo #4 regarding uniform revegetation activities and stormwater/erosion control management.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 9:** Continued from photo #8. See comments under photo #4 regarding uniform revegetation activities and stormwater/erosion control management.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 10:** Photo shows stormwater runoff controls (straw wattles) observed on the western perimeter of the Location. BMPs are no longer in proper functioning condition. Stormwater and erosion control measures are missing, or insufficient to stabilize the soils and manage runoff from the Location.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 11:** Photo taken southwestern end of the Location/disturbance area, facing northeast. Photo shows that stormwater and erosion control measures are missing, or insufficient to stabilize the soils and manage runoff from the Location.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 12:** Continued from photo 11. Photo shows areas of the Location where drill seeding was performed up the slope, rather than along the contour; seeding has not been performed in accordance with good engineering practices; stormwater and erosion control measures are missing, or insufficient to stabilize the soils and manage runoff from the Location.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 13:** Photo shows stormwater runoff controls (straw wattles) observed on the southwestern perimeter of the Location. BMPs are no longer in proper functioning condition. Stormwater and erosion control measures are missing, or insufficient to stabilize the soils and manage runoff from the Location.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 314707



**Photo 14:** Photo taken southwestern end of the Location/disturbance area, facing north. Photo shows that stormwater and erosion control measures are missing, or insufficient to stabilize the soils and manage runoff from the Location.