

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/19/2021

Submitted Date:

02/23/2021

Document Number:

696202352**FIELD INSPECTION FORM**Loc ID 398284 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Olson, Andrew		andrewolson@chevron.com	Principal Agent
Patterson, Chris		spwu@chevron.com	All Inspections per Olson

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231447	WELL	PA	05/15/2008	DA	103-09117	CARNEY 40X35	RI
398284	LOCATION	CL			-	CARNEY-62N102W 35SENW	RI

**General Comment:**

On 2/19/2021, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at Chevron USA Inc's Carney 40X35 location in Rio Blanco County, Colorado.

The following compliance issues were observed during this inspection:

1004.a: Final Reclamation

1002.f: Stormwater

Refer to the "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	<u>231447</u>	Type:	<u>WELL</u>	API Number:	<u>103-09117</u>	Status:	<u>PA</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>398284</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u>RI</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

## 1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

## Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed **Fail** \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control **Fail** \_\_\_\_\_

Non cropland: Revegetated 80% **Fail** \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: [Records show well PA 5/15/2008.](#)

[It was observed in this inspection that this Location does not meet COGCC 1004 reclamation requirements; Cable debris observed on the southwestern end of the Location; Large areas of the Location remain bare soil; erosion degradation evident \(see "Stormwater"\); desirable vegetative establishment is not progressing towards 1004.a.\(2\) requirements.](#)

Corrective Action:	<p style="color: red; margin: 0;">Comply with 1004 Rules: Remove debris and conduct additional reclamation activities; Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.</p>	Date <b>04/15/2021</b>
<div style="display: flex; justify-content: space-between; align-items: center;"> <span>Overall Final Reclamation <span style="color: red;">Fail</span></span> <span>Well Release on Active Location <input type="checkbox"/></span> <span>Multi-Well Location <input type="checkbox"/></span> </div>		
<b>Storm Water:</b>		
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs
<div style="display: flex; justify-content: space-between;"> <div style="width: 70%;"> <p>Comment: <span style="color: blue;">It was observed that stormwater and erosion control measures are missing, or insufficient; Erosion degradation observed on the southern areas of the Location.</span></p> <p><span style="color: blue;">Stormwater BMPs (straw wattles) observed no longer in proper functioning condition.</span></p> <p><span style="color: blue;">Erosion control BMPs to stabilize soils until long term stabilization on the Location can be achieved are missing or insufficient.</span></p> </div> <div style="width: 25%; align-self: center;"> <p>Date: <u>03/10/2021</u></p> </div> </div>		
<div style="display: flex; justify-content: space-between;"> <div style="width: 70%;"> <p>Corrective Action: <span style="color: red;">Comply with Rule 1002.f.(2) and install required stormwater and erosion control BMPs; ensure control measures are adequate for the site's conditions, installed in accordance with good engineering practices, and are maintained in a proper functioning condition. Ongoing stormwater management required until Location receives a passing final inspection.</span></p> </div> <div style="width: 25%; align-self: center;"> <p>Date: <u>03/10/2021</u></p> </div> </div>		
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202353	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5359000">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5359000</a>