

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/17/2021

Submitted Date:

02/23/2021

Document Number:

698600586

## FIELD INSPECTION FORM

 Loc ID: 407613  
 Inspector Name: St John, William (Cal)  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 66360  
 Name of Operator: ORM EXPLORATION CO  
 Address: 1125 OAK HILL RD  
 City: KELER State: TX Zip: 76248
**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Medina, Justin		justin.medina@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243452	WELL	PA	11/03/1983	OW	123-11243	LTJ PARTNERSHIP (OWP) 13-28	PA

**General Comment:**

This is an orphaned well inspection with emphasis on critical maintenance, verification and inventory of equipment, and identifying possible task required for potential well plugging and abandonment, flowline removal/abandonment, and equipment decommissioning/removal.

Inspection completed to document well site preparation for rig move in and start of plug and abandonment task.

Well is part of Orphaned Well Program all other open/required task for well/location abandonment remain open until completed and closed.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	No access road. Well was previously plugged and is located in active ag field. Used map to locate old access road and cut two track for access to well site.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:

Comment:	<input style="width: 50%;" type="text"/>	Date: _____
Corrective Action:	<input style="width: 50%;" type="text"/>	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Old production related debris in surrounding plowed field.		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Located surface casing and excavated. Extended surface casing to surface and installed wellhead.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 243452 Type: WELL API Number: 123-11243 Status: PA Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Previously plugged well will be re-entered and additional plugs placed to protect aquifers. Surface casing has been extended to surface and wellhead installed for rig work.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Planned work is to locate surface casing. Extend to surface and install wellhead. Located previously cut and capped surface casing. Excavated and exposed surface casing. Extended surface casing to surface and installed wellhead. Backfilled and leveled area. Site is ready for rig move in.	stjohnw	02/23/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600606	LTJ Partnership Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5359137">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5359137</a>