

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2021

Submitted Date:

02/24/2021

Document Number:

700405531**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 314619      Moran, Rick      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON ROADCity: RANGELY      State: CO      Zip: 81648**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email            | Comment |
|----------------|-------|------------------|---------|
| Sanford, Anita |       | atlx@chevron.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 229138      | WELL | TA     | 04/27/2017  | ERIW       | 103-06221 | UNION PACIFIC 43-28 | TA          |

**General Comment:**

A routine inspection identified the following compliance issues:

- 1) Gap in location berm on south edge. Photo 2. Complete by 4-1-2021.
- 2) Missing "911" on well sign. Photo 3. Complete by 4-1-2021.

Location is within a Rule 1202.d pronghorn winter concentration area.

This is a summary of inspection report 700405531.

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment: Missing "911" on well sign.

Corrective Action: Install sign to comply with Rule. Date: 04/01/2021

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                          |     |       |  |                 |
|--------------------------|-----|-------|--|-----------------|
| <b>Equipment:</b>        |     |       |  | corrective date |
| Type: Bradenhead         | # 1 |       |  |                 |
| Comment:                 |     |       |  |                 |
| Corrective Action:       |     | Date: |  |                 |
| Type: Deadman # & Marked | # 4 |       |  |                 |
| Comment:                 |     |       |  |                 |
| Corrective Action:       |     | Date: |  |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**Facility ID: 229138 Type: WELL API Number: 103-06221 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last MIT on 5-5-2017.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |

Comment: [Gap in location berm on south edge.](#)Corrective Action: [Install, maintain or provide documentation of post construction management plan or BMP's.](#)

Date: 04/01/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 700405532    | inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5359438">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5359438</a> |