

# Interim Reclamation and Stormwater Inspection

February 23, 2021

Operator: EDGE ENERGY II LLC- 10671

Location ID: 460397

Inspection Document #: 697502588

Weld County, CO

Lot 1 Section 1 T8N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Akbary /1A Pad  
Location ID: 460397



**Photo 1.** Photo taken south of the location, facing Northeast. Photo illustrates the Operator has initiated interim reclamation activities to reduce disturbance areas only needed for production operations. However, Operator has failed to complete interim reclamation activities (i.e., seed).



Inspection Photos  
Location Name: Akbary /1A Pad  
Location ID: 460397



**Photo 2.** Photo taken south of the location, facing North. See comment under Photo 1.



Inspection Photos  
Location Name: Akbary /1A Pad  
Location ID: 460397



**Photo 3.** Photo taken from the eastern location, facing North. See comment under Photo 1.



Inspection Photos  
Location Name: Akbary /1A Pad  
Location ID: 460397



**Photo 4.** Photo taken from the northern location, facing West. See comment under Photo 1. Photo illustrates rip-rap functioning as a check dam.



Inspection Photos  
Location Name: Akbary /1A Pad  
Location ID: 460397



**Photo 5.** Photo taken from the northeastern location, facing East. Photo illustrates rip-rap functioning as a check dams, which is directed to a stabilized outlet.



Inspection Photos  
Location Name: Akbary /1A Pad  
Location ID: 460397



**Photo 6.** Photo taken from the northeastern location, facing South. Photo illustrates the stabilized outlet, which appears to be in need of maintenance with the accumulation of sediment within the rip-rap material.



Inspection Photos  
Location Name: Akbary /1A Pad  
Location ID: 460397



**Photo 7.** Photo taken from the northeastern location, facing East. See comments under Photo 6.

