

**Inspection Photos**  
**Location Name: Paul Heinze #1 Flowline**  
**Spill ID: 479232**



**Photo 1 – Spill excavation area. Fencing present around open excavation.**



**Photo 2 – Spill excavation area. Fencing present around open excavation. Soils stored on site.**





**Inspection Photos**  
**Location Name: Paul Heinze #1 Flowline**  
**Spill ID: 479232**



**Photo 3 – Excavation for flowline repair.**



**Photo 4 – Free product present in open excavation.**





**Inspection Photos**  
**Location Name: Paul Heinze #1 Flowline**  
**Spill ID: 479232**



**Photo 5 – Impacted Soils stored on site.**



**Photo 6 –BMPs inadequate to prevent contamination of stormwater, surface water, Groundwater, and soil**





**Inspection Photos**  
**Location Name: Paul Heinze #1 Flowline**  
**Spill ID: 479232**



**Photo 7 – BMPs inadequate to prevent contamination of stormwater, surface water, Groundwater, and soil**



**Photo 8 – BMPs inadequate to prevent contamination of stormwater, surface water, Groundwater, and soil**

