

**Inspection Photos**  
**Location Name: Suckla-Brown Unit 17 Header**  
**Spill ID 478370**



**Photo 1 – Spill excavation with exposed flowline.  
Impacts still visible insitu.**



**Photo 2 – Spill excavation with exposed flowline.  
Impacts still visible insitu.**





**Inspection Photos**  
**Location Name: Suckla-Brown Unit 17 Header**  
**Spill ID 478370**



**Photo 3 – Spill excavation with exposed flowline.  
Impacts still visible insitu.**



**Photo 4 – Soils pile on Location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources