

Impetro Resources LLC, Marick State 2
121-10217


Inspection #688309732

2/17/2021

Routine Inspection



Colorado Oil and Gas Conservation Commission
39.81551, -103.18848, 4534.1ft, 304°
02/17/2021 02:49:13 PM



Colorado Oil and Gas Conservation Commission
39.81557, -103.18824, 4724.4ft, 326°
02/17/2021 02:49:30 PM



Colorado Oil and Gas Conservation Commission
39.81559, -103.18831, 4727.7ft, 320°
02/17/2021 02:49:23 PM



Colorado Oil and Gas Conservation Commission
39.81404, -103.19104, 4708.0ft, 327°
02/17/2021 02:51:52 PM



Colorado Oil and Gas Conservation Commission

39.81403, -103.19098, 4714.6ft, 310°


02/17/2021 02:52:04 PM




Colorado Oil and Gas Conservation Commission
39.81403, -103.19098, 4721.1ft, 13°
02/17/2021 02:52:09 PM



Colorado Oil and Gas Conservation Commission
39.81408, -103.191, 4727.7ft, 210°
02/17/2021 02:52:26 PM



Colorado Oil and Gas Conservation Commission
39.81409, -103.19099, 4734.3ft, 103°
02/17/2021 02:52:30 PM




Colorado Oil and Gas Conservation Commission
39.81409, -103.19097, 4731.0ft, 66°
02/17/2021 02:52:32 PM



PRODUCED
WATER
300 BBL'S

Colorado Oil and Gas Conservation Commission
39.81427, -103.19066, 4744.1ft, 83°
02/17/2021 02:53:22 PM



Colorado Oil and Gas Conservation Commission

39.81426, -103.19056, 4734.3ft, 133°

02/17/2021 02:53:31 PM