

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 334732

Network:Feb 24, 2021 at 12:51:48 PM MS  
Local:Feb 24, 2021 at 12:51:48 PM MS



Photo #2958 from entrance to location.

Network:Feb 24, 2021 at 12:51:51 PM MS  
Local:Feb 24, 2021 at 12:51:51 PM MS



Photo #2959 from entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 334732



Photo #2960 Flow line heating insulation open ended and not capped.



Photo #2961 Flow line heating insulation open ended and not capped.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 334732



**Photo #2962 Flow line heating insulation open ended and not capped.**

**Photo #2963 Multiple holes in tank containment liner**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 334732



**Photo #2964 Multiple holes in tank containment liner**