

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /21-9C (PJ-21)

Location ID: 427395



Photo #2966 from entrance to location.



Photo #2967 from entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /21-9C (PJ-21)

Location ID: 427395



Photo #2968 Stained soils under ECD fluid knock out drain valve.