

Inspection Photos
Location Name: GUILDNER #1
Location ID: 317889
Remediation Project No. 16185



Photo 1 – Location sign



Photo 2 – Location photo

Inspection Photos
Location Name: GUILDNER #1
Location ID: 317889
Remediation Project No. 16185



Colorado Oil and Gas Conservation Commission
40.12934, -104.8602, 4901.7ft, 36°
02/23/2021 10:51:26 AM

Photo 3 – NFPA label peeling from crude oil tank and no longer legible.



Colorado Oil and Gas Conservation Commission
40.12902, -104.86026, 4910.7ft, 295°
02/23/2021 10:58:29 AM

Photo 4 – Location photo

Inspection Photos
Location Name: GUILDNER #1
Location ID: 317889
Remediation Project No. 16185



Photo 5 – Location photo



Photo 6 – Stained soil observed at separator

Inspection Photos
Location Name: GUILDNER #1
Location ID: 317889
Remediation Project No. 16185



Photo 7 – Produced water vault. Weeds observed in Insp. Doc#697601087 have been removed.



Photo 8 – Cracks/staining visible on produced water vault.

Inspection Photos
Location Name: GUILDNER #1
Location ID: 317889
Remediation Project No. 16185



Photo 9 – Cracks/staining visible on produced water vault.



Photo 10 – Cracks/staining visible on produced water vault.

Inspection Photos
Location Name: GUILDNER #1
Location ID: 317889
Remediation Project No. 16185



Photo 11 – Former pit area. No evidence of work preformed for Remediation Project No. 16185.

