

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2021

Submitted Date:

02/25/2021

Document Number:

691201415**FIELD INSPECTION FORM**Loc ID 317889 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gintautas, Peter		peter.gintautas@state.co.us	
Knop, Max	303-825-4822	MKnop@kpk.com	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240128	WELL	PR	03/01/2020	OW	123-07916	GUILDNER 1	EI
478661	TANK BATTERY	AC	11/30/2020		-	Guildner 1 & 2 battery	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: [NFPA label peeling from crude oil tank and no longer legible.](#)Corrective Action: [Install sign to comply with Rule 605.](#)Date: 04/25/2021Overall Good: ☐**Spills:**

Type	Area	Volume		
Condensate				
Comment: Staining at concrete vault, separator; see photo log.				
Corrective Action: Properly treat or dispose of oily waste in accordance with 905.e.			Date:	<u>03/10/2021</u>

In Containment: No

Comment: [Produced water vault shows multiple cracks and integrity issues.](#)☒ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	240128	Type:	WELL	API Number:	123-07916	Status:	PR	Insp. Status:	EI
Facility ID:	478661	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: COGCC inspection of pit closure/produced water vault removal for Remediation Project #16185. Listed start date for site investigation is 2/15/2021. Vault is still in place and shows signs of compromised integrity. Inspection found no evidence of site investigation (photos 7-10).

Corrective Action: Per Rule 913.d.(2) Operator shall submit a Supplemental Form 27 with an updated Implementation Schedule at least 14 days in advance.

Date: 02/01/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201416	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5361548