

**Inspection Photos**  
**Location Name: John Weigandt Consolidation**  
**Spill ID 465402**



**Photo 1 – Spill area. Pipe and additional debris on left on location**



**Photo 2 – Pipe and additional debris on left on location**



**Inspection Photos**  
**Location Name: John Weigandt Consolidation**  
**Spill ID 465402**



**Photo 3 – Fence down around open excavation**



**Photo 4 – Fence down around open excavation**





**Inspection Photos**  
**Location Name: John Weigandt Consolidation**  
**Spill ID 465402**



**Photo 5 – Repaired flowline in open excavation**



**Photo 6 – Soils stored on location**






**Inspection Photos**  
**Location Name: John Weigandt Consolidation**  
**Spill ID 465402**



**Photo 7 – Soils stored on location**



**Photo 8 – Soils stored on location**





**Inspection Photos**  
**Location Name: John Weigandt Consolidation**  
**Spill ID 465402**



**Photo 9 – Stained soil visible on location outside of excavation area**



**Photo 10 – Stained soil visible on location outside of excavation area**

