

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335577**



**Location shows signs of lack of stabilization BMP's
in some areas (rutting is present).**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335577**



**Location shows signs of lack of stabilization BMP's
in some areas (rutting is present).**



**Location shows signs of lack of stabilization BMP's
in some areas (rutting is present).**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335577**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335577**



Sediment build up in perimeter ditch.



Sediment build up in perimeter ditch.

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335577**



**N39.55096 W108.12064 Rut damage in ditch.
Water not draining off road into culvert or ditch.**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335577**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**N39.55348 W-108.11985 Erosion damage
from culvert outlet.**

CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335577



**N39.55348 W-108.11985 Erosion damage
from culvert outlet.**