

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/24/2021

Submitted Date:

02/25/2021

Document Number:

700405547**FIELD INSPECTION FORM**
 Loc ID 335947 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 110 W 7TH STREETCity: FORT WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
West, Jerry		jerry_west@xtoenergy.com	
Clark, Erin	405-319-3250	erin_clark@xtoenergy.com	
Dooling, Jessica	970-675-4122	jessica_dooling@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298212	WELL	PR	05/10/2010	GW	103-11360	PICEANCE CREEK UNIT 297-10810	PR
298213	WELL	PR	02/01/2019	GW	103-11361	PICEANCE CREEK UNIT 297-10B9	PR
298214	WELL	PR	01/26/2011	GW	103-11362	PICEANCE CREEK UNIT 297-10B8	PR
298215	WELL	PR	02/01/2011	GW	103-11363	PICEANCE CREEK UNIT 297-10B7	PR
298216	WELL	PR	05/12/2010	GW	103-11364	PICEANCE CREEK UNIT 297-10B6	PR
298217	WELL	PR	01/26/2011	GW	103-11365	PICEANCE CREEK UNIT 297-10B5	PR
298218	WELL	PR	05/10/2010	GW	103-11366	PICEANCE CREEK UNIT 297-10B4	PR
298219	WELL	PR	02/01/2020	GW	103-11367	PICEANCE CREEK UNIT 297-10B3	PR
298220	WELL	PR	05/06/2010	GW	103-11368	PICEANCE CREEK UNIT 297-10B2	PR
298221	WELL	PR	02/16/2011	GW	103-11369	PICEANCE CREEK UNIT 297-10B1	PR

General Comment:

Routine well inspection.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location sign.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	RTU building.		
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical containers.		
Corrective Action:		Date:	
Type: Bradenhead	# 10		

Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	298212	Type:	WELL	API Number:	103-11360	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	298213	Type:	WELL	API Number:	103-11361	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	298214	Type:	WELL	API Number:	103-11362	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	298215	Type:	WELL	API Number:	103-11363	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	298216	Type:	WELL	API Number:	103-11364	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	298217	Type:	WELL	API Number:	103-11365	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	298218	Type:	WELL	API Number:	103-11366	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	298219	Type:	WELL	API Number:	103-11367	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Facility ID:	298220	Type:	WELL	API Number:	103-11368	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID:	298221	Type:	WELL	API Number:	103-11369	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts		Material Handling And Spill Prevention		
Ditches						

Comment: 2" of snow on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700405548	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5361784