

Inspection Photos

Operator: Hilcorp Energy
API: 067-08075
Date: 2/24/2021



Photo 1. View of the eastern project area from the southwestern corner facing center.



Photo 2. View of the western project area facing northward. Vegetation appears to be progressing in with smooth brome. Snow covered areas need to be assessed during the active growing season.



Photo 3. View of the reference area comprised of perennial irrigated grasses such as smooth brome, partially snow covered at this time.



Photo 4. View of closed gate after leaving location.