

Inspection Photos
Operator: Hilcorp Energy
API: 067-09459
Date: 2/24/2021



Photo 1. View of the well pad entrance facing center.



Photo 2. View of the western project area facing southward. Snow covered areas need to be assessed during the active growing season.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of the reference area comprised of perennial irrigated grasses such as smooth brome, partially snow covered at this time.