

Inspection Photos

API: 011-06164

Operator: STRACHAN EXPLORATION INC

Inspection Date: 2/23/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06164 | Date: 2/23/2021

Inspection Photos



Photo 1. Facing toward the disturbance adjacent to the main road which had been previously cited. This area was repaired however vegetation has not established and the BMP's are degraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021

Inspection Photos



Photo 2. The wattles and straw blanket are degraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021

Inspection Photos



Photo 3. Facing toward the disturbance adjacent to the main road which had been previously cited. This area was repaired however vegetation has not established and the BMP's are degraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021

Inspection Photos



Photo 4. The netting from the straw blanket needs to be removed in areas with out pulling up vegetation. Bare areas need to be reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021

Inspection Photos



Photo 5. Facing northwest toward along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021

Inspection Photos



Photo 6. Facing toward the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021

Inspection Photos



Photo 7. Facing toward the wellhead. Sign is posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06060 | Date: 2/23/2021