

Inspection Photos

API: 011-06019

Operator: OXY USA INC

Inspection Date: 2/23/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06019 | Date: 2/23/2021

Inspection Photos



Photo 1. Facing west toward the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06019 | Date: 2/23/2021

Inspection Photos



Photo 2. Facing west along the access road. The access road needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06019 | Date: 2/23/2021

Inspection Photos



Photo 3. Facing northwest toward the location. The area circled is where straw blanket was installed. Vegetation grew really well compared to other areas without strawblanket.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06019 | Date: 2/23/2021

Inspection Photos



Photo 4. View of groundcover where blanket was installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06019 | Date: 2/23/2021

Inspection Photos



Photo 5. Facing east at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06019 | Date: 2/23/2021

Inspection Photos



Photo 6. Facing southeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06019 | Date: 2/23/2021

Inspection Photos



Photo 7. Facing north toward the surrounding undisturbed area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06019 | Date: 2/23/2021