

Inspection Photos

API: 011-06024

Operator: OXY USA INC

Inspection Date: 2/23/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06024 | Date: 2/23/2021

Inspection Photos



Photo 1. Facing west toward the access road which has not been reclaimed. It appears topsoil has been spread along the road and at areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06024 | Date: 2/23/2021

Inspection Photos



Photo 2. Facing west toward the access road near the location. It appears topsoil has been spread along the road and at areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06024 | Date: 2/23/2021

Inspection Photos



Photo 3. Facing east at the location where topsoil has been spread out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06024 | Date: 2/23/2021

Inspection Photos



Photo 4. Facing east at the location. Trucks have hauled in topsoil to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06024 | Date: 2/23/2021

Inspection Photos



Photo 5. Facing northwest at the location where reclamation was previously performed. The plastic netting from the blanket is bunched up in areas and should be cut and removed without pulling up the vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06024 | Date: 2/23/2021

Inspection Photos



Photo 6. Facing southwest at the location. Vegetation has grown in very well where straw blanket was installed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06024 | Date: 2/23/2021