

Inspection Photos

API: 011-06036

Operator: OXY USA INC

Inspection Date: 2/23/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06036 | Date: 2/23/2021

Inspection Photos



Photo 1. Facing northeast toward the location. Straw blanket was installed on most of the location. Vegetation has grown in very well where straw blanket was installed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06036 | Date: 2/23/2021

Inspection Photos



Photo 2. View of vegetation cover where straw blanket was installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06036 | Date: 2/23/2021

Inspection Photos



Photo 3. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06036 | Date: 2/23/2021

Inspection Photos



Photo 4. The plastic netting from the blanket is bunched up in areas and should be cut and removed without pulling up the vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06036 | Date: 2/23/2021