

# Inspection Photos

API: 099-06868

Operator: LAMAR OIL & GAS EXPLORATION

Inspection Date: 2/23/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 099-06868 | Date: 2/23/2021

## Inspection Photos



**Photo 1.** Facing west toward the reclaimed access road. Vegetation has uniformly re-established.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06868 | Date: 2/23/2021



## Inspection Photos



**Photo 2.** Facing north at the center of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06868 | Date: 2/23/2021



## Inspection Photos



**Photo 3.** Facing south at the center of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06868 | Date: 2/23/2021



## Inspection Photos



**Photo 4.** Plywood debris has not been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06868 | Date: 2/23/2021



## Inspection Photos



**Photo 5.** Facing east at the north side of the location. This area has not established vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06868 | Date: 2/23/2021



## Inspection Photos



**Photo 6.** Facing west toward the surrounding undisturbed area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06868 | Date: 2/23/2021