

Inspection Photos

API: 099-06138

Operator: OXY USA INC

Inspection Date: 2/23/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06138 | Date: 2/23/2021

Inspection Photos



Photo 1. Facing north along the former access road at Lat/Long:37.87672,-102.72188. This area of the road has eroded and needs to be repaired and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06138 | Date: 2/23/2021

Inspection Photos



Photo 2. Facing north along the former access road at Lat/Long:37.87672,-102.72188. This area of the road has eroded and needs to be repaired and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06138 | Date: 2/23/2021

Inspection Photos




Photo 3. Facing west toward the location. There are two pipe risers that remain at the location shown at red arrows. Vegetation has not re-established near the risers.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06138 | Date: 2/23/2021

Inspection Photos



Photo 4. Facing northwest at the location. Vegetation has not re-established in this area. Soil may be compacted in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06138 | Date: 2/23/2021

Inspection Photos



Photo 5. Facing toward the pipe riser at the west side of the location. All equipment/risers need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06138 | Date: 2/23/2021

Inspection Photos



Photo 6. Another pipe riser associated with the well site was found at Lat/Long:37.87789,-102.71800. All equipment/risers need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06138 | Date: 2/23/2021