

Inspection Photos

Location Name: LARAMIE ENERGY LLC Hawkins Ranch /10-4 Pad

Location ID: 334520



Photo #2992 from entrance to location.



Photo #2995 Sediment has been transported off of location due to snow plowing.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Hawkins Ranch /10-4 Pad

Location ID: 334520



Photo #2996 Sediment has been transported off of location due to snow plowing.



Photo #2997 No BMP's located between the edge of fill slope and Sediment pile.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Hawkins Ranch /10-4 Pad

Location ID: 334520



Photo #2998 No BMP's to control Sediment run off of location.



Photo #2999 Sediment has been transported off of location due to snow plowing.