

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TIPPING-67S96W /34NWNW

Location ID: 334094



Photo #3008 from entrance to location.



Photo #3009 from entrance to location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC TIPPING-67S96W /34NWNW

Location ID: 334094



**Photo #3010 Multiple places with flow line heating insulation open ended and not capped.**



**Photo #3011 Rutting present on location due to lack of stabilization.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC TIPPING-67S96W /34NWNW

Location ID: 334094



**Photo #3012** Rutting present on location due to lack of stabilization.



**Photo #3013** No form of tracking control at entrance to location.