

**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 34SWNE  
Location # 335164**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 34SWNE  
Location # 335164**



**No evidence of tracking control BMP's**

**No evidence of tracking control BMP's**

**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 34SWNE  
Location # 335164**



**No evidence of tracking control BMP's**



**No evidence of tracking control BMP's**

**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 34SWNE  
Location # 335164**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 34SWNE  
Location # 335164**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 34SWNE  
Location # 335164**



**Road ditch needs maintained.**

**Road ditch needs maintained.**

**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 34SWNE  
Location # 335164**



**Road ditch needs maintained.**



**Road ditch needs maintained.**

**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 34SWNE  
Location # 335164**



**Erosion subsidence crack along up hill road  
into location.**



**Erosion subsidence crack along up hill road  
into location.**

**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 34SWNE  
Location # 335164**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC  
FEDERAL-66S96W 34SWNE  
Location # 335164**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**