

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWNE
Location # 335654**



Sign is weathered.



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWE
Location # 335654**



No battery sign at tank battery.



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWNE
Location # 335654**



Cattle cleaned out on main road.



Wattle repaired or replaced.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWN
Location # 335654**



Unmarked deadman



**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWNE
Location # 335654**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWE
Location # 335654**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWE
Location # 335654**



Check dam basin needs maintained.



Riprap needs maintained.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWE
Location # 335654**



Perimeter berm behind tank battery is not consistent.



Washing over bank of location behind tank battery.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWN
Location # 335654**



Channeling through perimeter berm.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWN
Location # 335654**



**Culvert before entrance needs maintained.
39.529205 108.131077**



**Unable to see culvert outlet. Sediment
being bladed off shoulder of road.**

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWNE
Location # 335654**



Unable to see culvert outlet.



Sediment being bladed off shoulder of road.

**TEP ROCKY MOUNTAIN LLC
CHEVRON-66S96W 17NWE
Location # 335654**



Road ditch needs maintained.



Road ditch needs maintained.