

CAERUS PICEANCE LLC

Parachute Creek /5A

Location # 335781



No evidence of tracking control BMP's



CAERUS PICEANCE LLC
Parachute Creek /5A
Location # 335781



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

CAERUS PICEANCE LLC
Parachute Creek /5A
Location # 335781



**Sediment build up in ditch from entrance
running behind location.**

CAERUS PICEANCE LLC
Parachute Creek /5A
Location # 335781



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



CAERUS PICEANCE LLC
Parachute Creek /5A
Location # 335781



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

CAERUS PICEANCE LLC
Parachute Creek /5A
Location # 335781



Ditch along road to lower well pad loosely compacted.



Sediment movement down road to lower pad.

CAERUS PICEANCE LLC
Parachute Creek /5A
Location # 335781



**Road and location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



Ditch along road to lower well pad needs maintained.

CAERUS PICEANCE LLC
Parachute Creek /5A
Location # 335781



Culvert before entrance needs maintained.
39.529205 108.131077



Unable to see culvert outlet. Sediment
being bladed off shoulder of road.

CAERUS PICEANCE LLC
Parachute Creek /5A
Location # 335781



Unable to see culvert outlet.



Sediment being bladed off shoulder of road.

CAERUS PICEANCE LLC
Parachute Creek /5A
Location # 335781



Road ditch needs maintained.



Road ditch needs maintained.